

IB m  
9-17

8-13  
22

Aer-5123/264

25 OCT 1956

SECOND ENDORSEMENT on NATC PaxRiv Md AAR ser 18-56 concerning A4D-1, BuNo 137816, accident occurring 13 Aug 1956, pilot LONG

From: Chief, Bureau of Aeronautics  
To: Chief of Naval Operations (OP-57)  
Via: Director, U. S. Naval Aviation Safety Center

Subj: Naval Air Test Center, Patuxent River, Maryland Aircraft Accident Report 18-56; forwarding of

1. Forwarded, concurring with the conclusions and recommendations of the Aircraft Accident Board.
2. An investigation of the fuel control installed on the aircraft involved in this accident by the Wright Aeronautical Division revealed no discrepancies leading to the reported power loss. The fuel control has been shipped to Bendix for disassembly and inspection. Further comments or action, as necessary, on this item will be initiated upon receipt of the results of the investigation being conducted by Bendix.
3. With reference to recommendation (1) of the basic report, increased throttle friction and a positive idle throttle detent will be incorporated by the contractor in all A4D-1 aircraft prior to delivery to the fleet. It should be noted that the above throttle difficulties had been under investigation by the Bureau of Aeronautics and the Douglas Aircraft Company prior to this accident.
4. The installation of a manual emergency stores jettisoning system, as mentioned in recommendation (2) of the basic report, is not considered practicable in that a redesign of the Aero 7A and 20A racks would be involved. The routing of cables through the pressurized cockpit and through the wing panel fuel cells to effect a manual system installation would be both difficult and extensive. Also, the effects of temperature changes and vibrational forces would tend to reduce the reliability of such a system. In lieu of the above, it is considered that an emergency release system incorporating a "one-shot" battery would be more appropriate. In order to further evaluate the need for a manual system, the Bureau of Aeronautics has requested the contractor to submit recommendations for an emergency stores jettisoning system.

1

PAXRIV  
UNDO

By direction

FTOL  
A25/1, ALD  
Ser 292

14 SEP 1956

FIRST ENDORSEMENT on NATC PaxRiv Md AAR ser 18-56 concerning ALD-1,  
BuNo. 137816, accident occurring 13 Aug 1956, pilot LONG

From: Commander, Naval Air Test Center, Patuxent River, Md.  
To: Chief of Naval Operations (OP-57)  
Via: (1) Chief, Bureau of Aeronautics  
(2) Director, U. S. Naval Aviation Safety Center  
Norfolk, Va.

Subj: Naval Air Test Center, Patuxent River, Maryland Aircraft  
Accident Report 18-56; forwarding of

1. Forwarded concurring with the conclusions and recommendations of  
the Aircraft Accident Board.

*C. H. Duerfeldt*  
C. H. DUERFELDT

Copy to:  
NAVAVSATCEN, NorVa  
BAR, El Segundo  
BAR, Woodridge

2



PART I - GENERAL

1. AIRCRAFT ACCIDENT BOARD CONVENED BY: <b>Naval Air Test Center, PaxRiv, Md.</b>		2. DATE OF ACCIDENT <b>13 Aug 1956</b>	TIME <b>1001EDT</b>	3. AIR SERIAL NUMBER <b>18-56</b>
4. TO: <b>CHIEF OF NAVAL OPERATIONS (Op-57)</b>		5. ENCLOSURES: (1) CAPT (b) (6) Statement		
6. VIA: (1) Chief, BuAer (Aer-512)		(2) M/Sgt (b) (6) Statement		
(2) Director, NavAvSafGen		(3) (b) (6) AD3 Statement		
(3)		(4) (b) (6) BMC, Statement		
(4)		(5) (b) (6) BM2, Statement		
(5)		(6) A/C Crash & Accident Report		
(6)		(7) LT (b) (6) Statement		
(LAST) DIRECTOR, U.S. NAVAL AVIATION SAFETY CENTER		(8) GDR (b) (6) Statement		
7. REPORTING CUSTODIAN (if different than item number 1): <b>Flight Test Division NATC, Patuxent River, Maryland</b>		(9) GDR Statement		
8. ACTIVITY OPERATED AIRCRAFT (if different than item 7): <b>Same</b>		11. LOCATION OF ACCIDENT: <b>in river 600 yds off end of runway 13 NAS PaxRiv</b>		
9. KIND OF FLIGHT <b>1K</b>		10. TIME OF DAY <input type="checkbox"/> DAWN <input checked="" type="checkbox"/> DAY <input type="checkbox"/> DUSK <input type="checkbox"/> NIGHT		12. ELEVATION ABOVE SEA LEVEL <b>0</b>
13. PLACE OF LAST TAKE-OFF <b>NAS Patuxent River, Maryland</b>		14. CLEARED FROM <b>NAS PaxRiv, Md. NAS PaxRiv, Md.</b>		
15. TYPE CLEARANCE: <input type="checkbox"/> IFR <input checked="" type="checkbox"/> VFR <input checked="" type="checkbox"/> LOCAL <input type="checkbox"/> OPERATIONAL <input type="checkbox"/> AIRWAYS <input type="checkbox"/> DIRECT <input type="checkbox"/> OTHER (Specify)				

16. TIME IN FLIGHT <b>00+25</b>	17. TYPE ACCIDENT <b>B-7</b>	18. PHASE OF FLIGHT <b>7</b>
19. MODEL <b>A4D-1</b>	20. SERIAL NUMBER <b>137816</b>	21. DAMAGE TO AIRCRAFT <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D
22. DOLLAR COST <b>\$628,000.</b>		23. AIRSPEED (Kts) <b>Est 100-120</b>
24. A/C WEIGHT <b>Est 15,250</b>		
25. LIST MODEL, SER. NOS., REPORTING CUSTODIAN AND DAMAGE CLASSIFICATION OF ANY OTHER A/C INVOLVED (complete separate OPNAV Form 3750-1 for each A/C)		

1. PERSONNEL	2. NAME (Last, first and middle initial)	3. RANK/RATE	4. FILE/SER. NO. DESIGNATION	5. DATE DESIGNATED	6. DATE OF BIRTH AGE
PILOT (Person at controls at time of accident)	<b>LONG, John O.</b>	<b>LT</b>	<b>(b) (6)</b>	<b>4/17/45</b>	<b>6/18/22 34</b>
CO-PILOT					
6. PERSONNEL	9. OPERATIONAL FLIGHT TRAINER		10. UNIT TO WHICH ATTACHED		11. TYPE INSTRUMENT CARD
	AVAILABLE?	USED?			
PILOT	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	<b>Flight Test Division NATC Patuxent River, Md.</b>		<input checked="" type="checkbox"/> STANDARD <input type="checkbox"/> SPECIAL
CO-PILOT	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO			<input type="checkbox"/> STANDARD <input type="checkbox"/> SPECIAL

TOTAL PILOT HOURS	ITEM			ITEM		
	PILOT	CO-PILOT	STUDENT	PILOT	CO-PILOT	STUDENT
ALL MODELS	<b>4535.9</b>	<b>57.1</b>	<b>Since Nov '52</b>	CV LANDINGS DAY/NIGHT	<b>125/0</b>	-
ALL MODELS IN LAST 12 MONTHS	<b>171.2</b>	<b>31.2</b>	-	FCLP LANDINGS DAY/NIGHT	<b>460/5</b>	-
ALL MODELS IN LAST 3 MONTHS	<b>70.1</b>	<b>21.1</b>	-	INSTRUMENT HOURS, LAST 3 MONTHS	<b>28.2</b>	-
ALL SERIES THIS MODEL	<b>22.4</b>	-	-	NIGHT HOURS, LAST 3 MONTHS	<b>14.6</b>	<b>8.5</b>
ALL SERIES THIS MODEL, LAST 12 MONTHS	<b>22.4</b>	-	-	(jet accidents only) TOTAL JET PILOT HOURS	<b>Since Nov '52</b>	<b>322.6</b>
ALL SERIES THIS MODEL, LAST 3 MONTHS	<b>21.2</b>	-	-	DATE LAST FLIGHT, ALL SERIES THIS MODEL	<b>8/10/56</b>	-
				DURATION LAST FLIGHT, ALL SERIES THIS MODEL	<b>2.0</b>	-

13. ALL PERSONNEL	NAME (last, first and middle initial)	RANK/RATE	FILE/SERVICE NO.	ORG. TO WHICH ATTACHED	INSTR. CODE	BILLET	POSITION
1.	<b>LONG, John O.</b>	<b>LT</b>	<b>(b) (6)</b>	<b>Flight Test NATC A</b>			<b>Pilot Center</b>
2.							<b>Cockpit</b>
3.							
4.							
5.							

(if additional space is necessary, attach additional sheet(s))

## AIRCRAFT ACCIDENT REPORT

OPNAV REPORT 3750-1

1. CEILING 200-0		2. VISIBILITY 8		3. WIND DIRECTION AND VELOCITY S 4		4. TEMPERATURE 84°F		5. DRY POINT 72°F		6. ALTITUDE SETTINGS 30.03	
7. OTHER WEATHER CONDITIONS (winds aloft, icing levels, state of sea, etc., if pertinent to accident)											

ITEM	P	S	ITEM	P	S	ITEM	P	S
PILOT ERROR			LANDING SIGNAL OFFICER ERROR			MATERIAL FAILURE OR MALFUNCTION		
CREW ERROR			OTHER PERSONNEL ERROR, Specify.....			MATERIAL INADEQUACY		
SUPERVISORY PERSONNEL ERROR			ADMINISTRATIVE ERROR			ROLLING AND PITCHING DECK/ROUGH SEAS		
MAINTENANCE PERSONNEL ERROR			AIRPORT OR CARRIER FACILITIES			UNDETERMINED		X
SERVICING PERSONNEL ERROR			WEATHER			OTHER, Specify.....		

FOR ACCIDENTS ABOARD DEPLOYED CARRIERS (Complete following Section on Pilot.)

1. DATE DEPLOYED	2. DAY - HOURS/LANDINGS LOGGED SINCE DEPLOYED	3. DAY - HOURS/LANDINGS LOGGED LAST 30 DAYS
4. INSTRUMENT HRS. LOGGED SINCE DEPLOYMENT	5. NIGHT - HOURS/LANDINGS LOGGED SINCE DEPLOYED	6. NIGHT - HOURS/LANDINGS LOGGED LAST 30 DAYS

## PART II - MAINTENANCE, MATERIAL AND FACILITIES DATA

1. AIRCRAFT HISTORY		DATE OF MANUFACTURE	SERVICE TOUR	MONTHS IN THIS TOUR	TOTAL NO. OF OVERHAULS	FLIGHT HRS. SINCE LAST OVERHAUL	FLIGHT HRS. SINCE ACCEPTANCE	TYPE CHECK LAST PERFORMED	FLIGHT HRS. SINCE LAST CHECK	NO. OF DAYS SINCE LAST CHECK
		12/24/55	1	17	0	0	212.0	2nd Major	20.7	7
		ENGINE MODEL	SERIAL NO. OF ENGINE							
		J65-W16	611002	0	0	114.3	A	20.7	7	

a. DID FIRE OCCUR: <input type="checkbox"/> BEFORE ACCIDENT <input type="checkbox"/> AFTER ACCIDENT <input checked="" type="checkbox"/> DID NOT OCCUR		b. DID EXPLOSION OCCUR IN FLIGHT? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
c. CHECK IF APPLICABLE <input type="checkbox"/> AMP FOR SERIAL		d. HAS DTR BEEN REQUESTED? <input type="checkbox"/> YES <input type="checkbox"/> NO	
e. FAILED COMPONENTS INVOLVED			

CHECK BELOW ITEMS PRESENT IN THIS ACCIDENT

a. <input type="checkbox"/> AIRCRAFT DESIGN	d. <input checked="" type="checkbox"/> UNDETERMINED	g. <input type="checkbox"/> SURFACE FACILITIES
b. <input type="checkbox"/> AIRCRAFT EQUIPMENT	e. <input type="checkbox"/> TECHNICAL INSTRUCTION	h. <input type="checkbox"/> HUMAN ENGINEERING (e.g. cockpit configurations)
c. <input type="checkbox"/> MAINTENANCE	f. <input type="checkbox"/> OTHER, Specify.....	

6. ALTITUDE AT MALFUNCTION 1000 ft	5. AIR SPEED Est 150	7. OPERATING TEMPERATURE	8. WEIGHT OF AIRCRAFT 15,250	9. C.G. (% MAC)	10. KIND OF FUEL	11. FUEL PRESSURE
12. EVIDENCE OF FUEL CONTAMINATION Undetermined				13. CAUSE OF ENGINE FAILURE OR FLAMEOUT		
14. FUEL CONTROL REGULATOR/CARBURETOR (List Stock and Ser. Nos., give time since new or overhauled)				15. EXTERNAL STORES ABOARD A/C 2-150 gal external tanks		

(If additional space is necessary, attach additional sheet(s))



## AIRCRAFT ACCIDENT REPORT

## PART II - MAINTENANCE, MATERIAL AND FACILITIES DATA (Cont'd)

SECTION B - FACILITIES DATA	1. GENERAL (CHECK BASIC FACILITIES INVOLVED, DESCRIBE EFFECT ON ACCIDENT IN THE ANALYSIS SECTION)								
	a. <input type="checkbox"/> CLEARANCE AUTHORITY	h. <input type="checkbox"/> RUNWAY		o. <input type="checkbox"/> EMERGENCY ARRESTING GEAR (Runway)					
	b. <input type="checkbox"/> FLIGHT PLANNING INFORMATION SOURCE	i. <input type="checkbox"/> WATER LANDING AREA		p. <input type="checkbox"/> AIRCRAFT SERVICING, HANDLING AND DIRECTING (Field or Ship)					
	c. <input type="checkbox"/> LANDING AIDS (GCA, CCA, ILS, etc)	j. <input type="checkbox"/> APPROACH ZONE		q. <input type="checkbox"/> CRASH AND RESCUE					
	d. <input type="checkbox"/> TRAFFIC CONTROL TOWER (Field or Ship)	k. <input type="checkbox"/> END ZONE		r. <input type="checkbox"/> SEARCH AND RESCUE					
	e. <input type="checkbox"/> APPROACH AND ENROUTE AIDS TO NAVIGATION	l. <input type="checkbox"/> SHOULDERS		s. <input type="checkbox"/> CATAPULT					
	f. <input type="checkbox"/> RUNWAY WATCH	m. <input type="checkbox"/> TAXIWAY		t. <input type="checkbox"/> ARRESTING GEAR (Carrier)					
	g. <input type="checkbox"/> LANDING SIGNAL OFFICER	n. <input type="checkbox"/> PARKING AREA		u. <input type="checkbox"/> BARRIER OR BARRICADE (Field or Ship)					
	w. <input type="checkbox"/> OTHER (Specify) .....			v. <input type="checkbox"/> FLIGHT DECK					
	8. EQUIPMENT INVOLVED: <input type="checkbox"/> CATAPULT <input type="checkbox"/> ARRESTING GEAR						5. PRESSURE SETTINGS	6. WIND OVER DECK	7. RELATIVE HEADING
f. MARK NUMBER		g. MODEL NUMBER		h. LOCATION ON SHIP		i. LAUNCHING BRIDLE AND CONFIGURATION USED			
j. CATAPULT/ARRESTING GEAR BULLETINS OR NOMOGRAMS USED									
k. This portion shall be completed whenever (1) a major aircraft accident involves arresting gear, barrier and/or barricade equipment, or (2) an aircraft accident involves malfunctioning of arresting gear, barrier and/or barricade equipment. Minor accidents or routine damage to cables, weldings and other expendable components need not be reported.									
ENGAGED		DECK RUNOUT (FT.)	RAM TRAVEL (IN.)	CONTROL VALVE SETTINGS		ACCUMULATOR PRESSURE (PSI)	COMMENTS (for cable failure specify number of landings and months in service)		
				CONSTANT PRESSURE		CONSTANT RUN-OUT (WT. LBS.)			
				DOME (P.S.I.)		RATIO			
DECK PENDANT									
DECK PENDANT									
BARRIER									
BARRIER									
BARRICADE									

PART SECTION	ITEM	PART III REMARKS (continue on separate pages if necessary)
Encl:	(10)	Medical Officers Report
	(11)	MAJ. (b) (6) Statement
	(12)	ICDR (b) (6) Statement
	(13)	(b) (6) AN, Statement
	(14)	Mr. (b) (6) 's Statement
	(15)	Mr. (b) (6) Statement
	(16)	(b) (6), AD3, Statement
	(17)	Mr. (b) (6) Statement
	(18)	Photographs (28 figures)
	(19)	Crash Location Chart

## PART IV - SIGNATURES (INDICATE DATE SUBMITTED TO C.O.)

(b) (6)	Ops Off.	(b) (6)	Project Pilot
(b) (6)	CDR, USN	ICDR, USN	UNIT BILLET
(b) (6)	(MC), CDR, USN	LT, USN	Project Pilot
	(Flight Surgeon member)	(member)	UNIT BILLET

## V The Accident

LT LONG departed the Flight Test line in A4D-1 BuNo 137816 at approximately 0930 EDT on 13 August 1956 for a 2.5 hour familiarization flight. A proper radio check was made with Flight Test Base Radio prior to leaving the line. He took off on runway 9, NAS Patuxent River, Md. at approximately 0935 EDT. At about 0958 EDT, the pilot called the tower that he was approaching the break for runway 9 and was cleared to break. He was observed to enter the break with landing gear down and drop tanks aboard at a normal speed for this configuration and at an estimated 1500 ft. altitude. The airplane was further observed on the downwind leg in a position to turn base leg for runway 9 and at about 1000 ft. of altitude. The airplane then commenced a wings nearly level, slightly nose high descent at a steep angle. It turned about 50°-60° to the left during the descent and struck the water in a wings level, nose high attitude with a high sink rate about 600 yds from the approach end to runway 13. The airplane hit, bounced once then sank almost immediately. Rescue operations started within 30 seconds as a helicopter was airborne about 200 yds from the point of impact.

## VI Damage to Aircraft

The aircraft sustained strike damage on impact with the water.

The lower portion of the after fuselage section and the extended main landing gear apparently struck the water first adding pitching velocity to the forward portion of the aircraft in addition to the high sinking velocity.

Major structural components and areas received the following damage:

Aft fuselage area - extensive impact damage along the lower surface from the tail disconnect station to the end of the airplane. Relatively little damage to the topside and horizontal tails surfaces or the upper fuselage.

Center fuselage area - extensive impact damage along entire lower surface. The engine was visible throughout this lower area. This section was held to the after fuselage section only by control cables and hydraulic lines. All normal connection fittings had failed.

Landing gear - the main landing gear structure and nose wheel structure failed very near the attachment points and were folded under the airplane and held in place by various hydraulic lines, fittings and bent pieces of airplane skin structure.



Wing area - the wing center section was separated in the middle, the main spar was broken and the wings ripped away from the fuselage attaching points. The left and right sections were held together by miscellaneous fuel and hydraulic lines and one steel spar cap about one inch by  $\frac{1}{4}$  inch. The fuel tanks were ripped off and split into many pieces. The underside of the wing was ripped and torn in several spots. The landing flaps pulled completely off of the starboard wing and were nearly off of the port wing.

Nose and cockpit area - the nose section up to the first bulkhead was completely torn off. From this point aft the left and right hand sides with consoles, separated laterally exposing the entire cockpit. Although the pilot's seat remained attached to the aircraft the bottom of the seat was completely ripped out.

The engine - suffered impact damage to the lower compressor case and at several other points on the exterior. The rotors and stators showed damage as a result of foreign objects entering the compressor. The rotors and stators were bowed and the interior of the lower compressor case was damaged as a result of the compressor case being forced upward and the rotor shifting forward on impact. The second stage turbine blades were bowed as a result of the shroud ring being forced upward on impact and impinging on the blades. The case of the fuel control was cracked on impact. All lines and fittings were severed either on impact or when the engine fell from the plane to the river bottom during salvage operations.

## VII The Investigation

With the assistance of Mr. (b) (6) of Douglas Aircraft Company, Mr. (b) (6) of Wright Aero Division and LCDR (b) (6) of the Naval Safety Center, the Accident Board made a thorough investigation of the wreckage in an effort to determine the cause of the accident. The main body of the aircraft and engine were recovered in approximately five hours. Diving operations were continued for two days and almost all parts of the aircraft were recovered.

The Board was divided into two groups - one group examined the airframe and systems, the other group examined the engine and associated components.

Statements of qualified observers who witnessed the flight path prior to the crash indicate a sudden loss of power while the plane was on the downwind leg of the traffic pattern.

The fuel system was examined and all fuel lines not destroyed by the impact both fluid carrying and vent, were



examined for blockage and found clear. The fuel shut-off valve was found in a semi-open position, but examination of the linkage to this valve indicated that it was forced to this position on impact. The control itself was in the fuel "on" position. The fuel transfer pump, the fuel boost pump, and engine driven pump were examined for possible malfunction. The transfer pump and the boost pump were functionally checked and were in operating condition. Investigation of the fuel transfer pump indicated no rotation on impact. The fuel tank guage was jammed at 4600 lb. Examination of the guage face under black light to determine a possibly different reading at time of impact gave negative results. The fuel transfer shut-off switch ( a test rig) was found in the "off" position when the airplane was recovered. The fuel transfer warning system functioned properly when checked. The fuel probe was returned to Douglas for examination and was found to function properly.

The hydraulic system was examined and all components of this system with the exception of the fluid carrying lines were intact on recovery. It was determined that the flaps were down, the landing gear was down and locked, the speed brakes were closed, and the hydraulic portion of the flight control system engaged at the time of impact. The aileron control valve and the elevator control valve were examined and found to be in workable condition. The longitudinal trim actuator was functionally checked and found to be in operating condition.

The engine was disassembled and jointly examined by Navy personnel, Wright Aeronautical representatives, and Bendix representatives. The investigation reveled the following:

1. Front Main Bearing Support

(a) Starter adapter was damaged when alternator drive assembly was torn loose during impact.

(b) Foreign matter, which was confirmed to be a mud sediment by laboratory analysis, was found to be present on inner cavity surfaces.

(c) The front main bearing suffered no impact damage and was in good condition.

(d) The front main bearing support and minor components with the exception of item (a) suffered no damage.

2. Center Main Bearing Support

(a) The center main bearing support and its minor components did not suffer any apparent damage as a result of the crash.

(b) The center main bearing was lightly contaminated with mud and was in initial stages of corrosion but did not display any evidence of distress. It was apparent that the bearing had been lubricated properly prior to the incident.

### 3. Rear Main Bearing

(a) The rear main bearing was lightly contaminated with mud and was in initial stages of corrosion, however, there was no evidence of bearing distress. It was apparent that the bearing had been lubricated properly prior to the incident.

### 4. Engine Gear Boxes and Lubrication System

(a) The component gear boxes and shafts were found to be in an operable condition and displayed no evidence of malfunction or rotational impact damage.

(b) Mud sediment deposits contaminated all components within the lubrication system.

(c) All components displayed evidence of proper lubrication and exhibited no areas of distress.

(d) The oil pump, modified to NEB 107, appeared to have been in an operable condition. Contamination by salt water, mud and fuel resulted in corrosion of inner cavity surfaces after exposure to atmosphere.

(e) It was evident that oil lines and passages within the oil system contained oil at the time of impact.

(f) Although a considerable amount of water was present in the oil tank, the quantity of oil within the tank and oil system was considered adequate for proper lubrication.

### 5. Compressor

(a) The compressor housing was intact although an impact puncture was found in the area adjacent to the primer solenoid.

(b) The compressor rotor was lightly damaged in all stages as a result of the crash impact.

(c) The appearance of the compressor was indicative of a very low RPM as evidenced by:

(1) Very slight or no bowing of rotor blades opposite to the direction of rotation.

(2) The major part of compressor blade damage occurring as a result of axial interference.

(3) No gouging of the upper compressor housing as compared to gouging of the lower housing at the 5 - 7 o'clock position.

(4) Limited damage to the inlet guide vanes and compressor rotor first stage blades from impact debris.

#### 6. Hot Section

(a) The combustion chamber inlet housing suffered impact damage at the 6 o'clock position which resulted in:

(1) A 20 inch opening along the weld which joins the front attaching flange to the housing body.

(2) Breaking away of the burner support strut locating block at the 6 o'clock position.

(b) The combustion chamber outer housing suffered a large impact dent at the bottom which protruded into the outer liner and dented it also.

(c) There was no evidence of combustion products or heat discoloration near any of the combustion chamber damage noted above, thereby supporting the conclusion that the engine was not operating at time of impact.

(d) The second turbine stator shroud suffered an impact dent at the 6 o'clock position which resulted in various degrees of tip damage to the second stage rotor blades. The first stage rotor was not damaged by the crash. The condition of the turbine supports the conclusion that the engine was not operating at time of impact.

(e) There was no evidence of overheating, abnormal combustion, metallization or other discrepancies within the hot section which would indicate improper functioning of the engine.

#### 7. Fuel System

(a) All filtering elements and lines within the fuel system were found to be clean with the exception of light mud deposits.

(b) Fuel Pump - The pump was disassembled and inspection revealed that it was in satisfactory condition. The inlet line from the airframe to the pump was severed during impact at the pump which allowed water and mud to enter the system at this point.



(c) Fuel Distributors - The No. 4 and No. 5 position distributors were broken loose during impact. The fuel lines at these locations were crushed; however, the lines from the other distributors to the fuel tubes contained fuel and water. It should be noted that the presence of fuel does not confirm that the engine was receiving fuel.

(d) Fuel Control - The control suffered minor impact damage to:

(1) the compressor pressure limiter assembly which was cracked at the mounting flanges,

(2) two external solenoids.

The control was found to contain some fuel and water on initial investigation, but no estimate of fuel quantity present in the control at time of impact could be made because of the cracked assembly. The control was returned to Curtis-Wright and the damaged components noted above were replaced with like servicable items. The results of the testing indicated no malfunctioning of the control under any of the variables (maximum flow, minimum flow, acceleration-deceleration, adjustment and correct functioning of altitude and temperature compensation devices) that might have been conducive to engine flame-out. 11

(e) The throttle was found in the idle cut-off position when the airplane was recovered. The position is not necessarily indicative of the position during flight as the manner in which the wreckage parted could easily have moved it to this position. The throttle linkage on the fuel control was found indicating 20° above "idle", however, the case had been cracked and this position is not necessarily indicative of the position during flight.

The autopsy examination revealed no evidence which would indicate that the pilot was overcome by carbon monoxide or that he suffered hypoxia (or anoxia).

### VIII The Analysis

Examination of the airplane and statements of witnesses definitely show that the airplane lost power while in the traffic pattern and that the engine was rotating at a very low RPM on impact.

Examination of the airplane revealed no mechanical reason for the accident.

Examination of the pilot revealed no medical reason for the accident.

The Board must assume that some malfunction caused the pilot to terminate the flight sooner than expected and further that whatever the reason it was of such a minor nature that the pilot did not inform the tower or cause him to make other than a normal entry to the pattern.

As no tangible evidence was found which could be labeled the prime cause factor the Board was forced to look for the most probable cause factors using the known facts. The outstanding fact of the investigation is that the engine was definitely not producing thrust at the time of impact and probably for a short period preceding impact. Therefore, the Board considers that there are two possible causes for the engine failure although in each case several reasons tend to refute the possibility.

The first possible cause is inadvertent placement of the throttle in the idle cut-off position. The reasons for such a cause are:

- (1) a known condition of low throttle friction.
- (2) a non-positive idle throttle stop
- (3) a weak spring arrangement designed to hold the throttle inboard and prevent its passing the idle throttle stop.

The reasons against such a possibility are:

- (1) The configuration and speed of the airplane at the "break" (wheels down, est. speed under 200 kts, heavy gross weight) point toward at least a moderate throttle setting with no reason to reduce throttle to the idle position.

- (2) The pilot was well aware of the low friction, condition of the throttle stop and weak spring arrangement.

The second possible cause is flameout due to fuel exhaustion as result of mismanagement of the transfer system. The reasons for such a possibility are:

- (1) The duration of the flight corresponds to the amount of fuel available in the sump tank.
- (2) The transfer switch was found in the off position.

The reasons against such a possibility are:

- (a) A red warning light located in the center of the instrument panel would glow any time the transfer switch



was off. The actuating pressure switch and the light both functioned properly following the accident.

(b) The fuel guage functions in such a manner that the guage shows total internal fuel remaining unless the level in the fuselage tank drops below 1100 lb. as would be the case if the transfer switch were off, the guage then drops out the wing fuel reading and shows fuselage tank fuel only. The fuel probe which actuates the guage in the above described manner functioned properly following the accident.

(c) A mixture of fuel and salt water were found in the sump tank following the accident, indicating the fuel was present in the fuselage tank prior to impact.

(d) The pilot was well aware of the function of the fuel transfer switch and of the meanings of the indications described above.

The Board notes the following item of airplane design which may have prevented a successful ditching. Electrical power is required to jettison external tanks by the normal or so called emergency method, thus preventing the pilot from reducing the airplanes gross weight in an emergency. Therefore, if engine RPM falls below generator drop out speed the pilot must extend the emergency generator and let it come up to speed before being able to jettison the external tanks.

#### IX Conclusions and Recommendations

13

It is concluded that:

- (1) The primary cause factor is complete power loss.
- (2) The reason for such power loss is undetermined.

It is recommended that:

- (1) The throttle quadrant be redesigned to provide greater friction and a positive idle stop.
- (2) A manual emergency stores jettisoning system be provided in order that pilots may jettison external stores regardless of electrical power.

STATEMENT OF CAPT (b) (6)

USA

At approximately 1000 hours EDT, 13 August 1956, I was returning from a project flight to the Flight Test helicopter ramp in an HUL-1 helicopter BuNo 142369. There were two helicopter crewmen riding in the helicopter with me, M/Sgt (b) (6) USMC, and (b) (6) (b) AD3, USN. I was flying east of, and parallel to, runway 31 at an altitude of approximately 75 feet when I first saw the A4D slightly to my right and at approximately the same altitude. At that time I noted that the landing gear of the A4D was down, speed was relatively slow, with a high angle of attack. The attitude was very similar to that used in FCLP's, and I assumed momentarily that this aircraft was engaged in field carrier landing practice on runway 13 although I wondered why the pilot was practicing on a closed runway. I did not see any smoke coming from the tailpipe or any other part of the aircraft. I did not note whether dive brakes or flaps were down. Aircraft heading was perpendicular to runway 13-31, estimated to be 220° magnetic. No attempt to turn from this heading was noted, and the aircraft contacted the water in the attitude stated above approximately 150 yards off shore from the approach end of runway 13. I saw some small unidentifiable pieces of the aircraft fly into the air upon contact with the water, and it immediately sank. I immediately flew to the scene, trying all the while to contact the tower on channel 1, but received no immediate response. There was a large surface area covered with fuel, with a few pieces of the aircraft floating. A helmet came to the surface, along with what appeared at the time to be the pilot. The helicopter I was flying was not equipped with a hoist, so I hovered over the scene, and the two crewmen jumped overboard. I contacted LT (b) (6) who was flying in the immediate area in an HOK-1 helicopter equipped with hoist. While talking to LT (b) (6) the tower answered and I informed the tower of the crash. Shortly thereafter the HOK, crash boat, and a UF arrived on the scene, and assuring myself that I could be of no further assistance I departed, landing at the Flight Test helicopter ramp at 1010 EDT.

(b) (6)

(b) (6)

CAPT, USA

14

Enclosure (1)



STATEMENT OF (b) (6) M/SGT, (b) (6) USMC

At approximately 1000 on 13 August 1956, I was a crew member on HUL helicopter BuNo 142369 piloted by CAPT (b) (6) USA. We were flying north and parallel with runway 13. Our position was approximately 600 hds from the north end of the runway when I just sighted an A4D-1 about 200 yds off the end of the runway and flying in a south westerly direction. The aircraft had about 60 ft to 70 ft of altitude in an FCLP type attitude with landing gear and flaps down and losing altitude fast. There appeared to be no tailpipe smoke when suddenly the aircraft nosed over sharply and struck the water in a steep nose down attitude and then porpoised back to the surface sending up a large spray of water and debris, then sank immediately. CAPT (b) (6) piloted our helicopter over the area at once and we sighted the pilot's helmet but could not tell whether or not he was wearing it because the water was so stirred up. I removed my helmet and shoes and jumped about 20 ft into the water near the helmet. But the helmet was not attached to the pilot, about 10 yds away I located the life raft and it was not attached to the pilot. Then I tried to dive down three or four times to locate the wreckage but could not get deep enough. By this time, the JP fuel and fumes were burning my body and blurring my eyes beyond good vision. I was in the water approximately 20 to 25 minutes when a boat from Flight Test picked me up.

(b) (6)

/SGT, USMC

15

Enclosure (2)

STATEMENT OF (b) (6) AD3, USN

On the morning of 13 August 1956, I was a crew member aboard HUL BuNo 142369 piloted by CAPT (b) (6), USA. At approximately 1000 EDT, flying parallel to runway 31, it was related to me that an A4D-1 had crashed about 100 yds off shore in the bay. The pilot of the HUL moved into the area at the same time the other crew member, (b) (6) M/Sgt, USMC and I started discarding clothing getting ready for an attempted rescue of the downed pilot. On the first pass of the HUL, Mayer jumped approximately 20 feet into the water and on the second pass I jumped 75 to 100 feet from him. Due to debris and JP fuel, it was difficult to see under water. What appeared to be a parachute and helmet were located but were not attached to the pilot. After remaining in the water approximately 20 to 25 minutes, I was picked up by a crash boat and transferred to a Flight Test boat which brought us back to the hangar area.

(b) (6)

(b) (6)

AD3, USN

16

Enclosure (3)



20 August 1956

STATEMENT OF (b) (6) MEC, USN, DIVER FIRST CLASS, CONCERNING  
AIRCRAFT CRASH ON 13 AUGUST 1956:

I descended approximately 1130 13 August 1956 to search for sunken aircraft, found same about fifteen minutes later.

I was instructed by (b) (6) BMC, USN, Master Diver to look for body of pilot first, which I did. The aircraft as I seen it to be appeared to be upside down, Stbd side lower in mud (upside down it would be port side down). I attached my hand line to the Stbd wing, and proceeded to fuselage, I started aft & when I reached the tail section, turned and started forward. (Visibility was bad because of mud bottom) I reached just fwd of wings and found that the aircraft was badly torn and wrecked, everything seemed to angle upwards (wiring & jagged metal badly mangled) atop of all this I located body of pilot in a sitting position all strapped in. (Helmet missing) I unlatched three buckles holding him and parachute pack together, also light colored strap seemed to lead back into wreckage which was also holding body to wreckage. I unbuckled two front straps high on chest of pilot also unbuckled strap on Stbd side of pilot. Secured pilot around chest under arms with securing line & rode to surface with body. Pilot's right leg was tangled in wreckage, but not to the extent that he could not free it if he was conscious and unstrapped. Body was about 20' under surface of water atop of fwd fuselage wreckage.

(b) (6)

MEC. USN.  
USN.

17

Enclosure (4)



2 August 1956

STATEMENT OF (b) (6) RM2, DIVER FIRST CLASS, CONCERNING AIRCRAFT  
CRASH ON 13 AUGUST 1956:

While working for (b) (6) BMC, Master Diver, USN, I descended at approximately 1125 to search for wrecked aircraft. Approximately 15 to 20 minutes later I located aircraft and secured my line to the tail section, then proceeded forward along the fuselage to the Port wing (which was on my right) the plane being upside down, I drew my conclusion of it being upside down by the word - "NAVY" - stenciled on the fuselage which was inverted. I explored the Port wing (Stb. wing) which seemed to be intact with very little or no damage, I then retraced myself back to the fuselage and with the intention of proceeding as far forward as possible, but just about at the forward part of the wing, the plane was broken off or what appeared so. At this point I went back to the surface, to inform the diver in charge, and to get further instructions, at this time divers were changed and I gave (b) (6) BMC, USN, MASTER DIVER, my report.

Later I was sent back down with, (b) (6) as a diving partner, our duty was to secure recovery wires to the plane for hoisting. We secured one wire to the tail hook (arresting gear) and another around the fuselage, the hoisting was done by the wire secured to the tail hook, the other wire was primarily as a safety measure. Most of the plane came up with the first hoist but the engine fell out and was recovered a few minutes later.

(b) (6)

18

Enclosure (5)

AIRCRAFT CRASH AND ACCIDENT REPORT  
PRNC-NATE-1901

CONTROL TOWER

DATE 13 August 1956	TIME 0903 EST	UNIT FLIGHT TEST
TYPE A/D	BURO 137816	PILOT LT. J. O. LONG
LOCATION OF ACCIDENT C-7 Station Crash Grid/ in the water approximately 1000 feet Off approach end runway 13		
DISTANCE TO SCENE Approx. 3600 ft from Operations	SERVICE NUMBER 9	
SKY CONDITION 20,000 thin scattered	VISIBILITY 8 miles	
WIND DIRECTION Southeast	WIND VELOCITY 4 knots	
TEMPERATURE 84.0°F	DEW POINT 72.1°F	
RELATIVE HUMIDITY 68%	TIME OF ALARM 0910EST	

Give clear and concise description of accident and tower statement.

FLORIDA 816 A/D called tower in the slot for R/W 9, tower cleared FLORIDA 816 to break call on base leg. No other transmissions were received from 816. As controller I watched 816 as he was passing over the EM Beach at about 900 feet with his gear in the down position. I then turned my attention to traffic on the field for about 20 seconds, looking again at the base leg position, I lost sight of 816 however I did sight a sizeable disturbance in the water and called it to the attention to another controller at the same time the water smoothed out and I sighted the red painted tail submerging. An HUL helicopter operating just past the intersection of R/W 20 & 13 spotted the crash and proceeded without instruction from the tower to the scene and was over the scene within seconds, he had no hoist gear aboard, however, two crewman aboard did jump out of (over)

OTHER PERSONNEL IN TOWER

(b) (6)	ACC	(b) (6)	ACAN	19
(b) (6)	ADC			
(b) (6)	AC2			
#1 (250.6 mcs)	TRACK NUMBER	0602		
(b) (6)			AC1	

NOTE - BUFO, PRNC, NATE-1, D. 1.

Enclosure (6)



the HUL into the water. At the same time there was a crash boat and a UF (TEAKETTLE 933) operating in the PAXRIV Seadrome who also sped to the scene and arrived within two minutes after the crash. An HOK without hoist gear appeared on the scene.

20

TO WHOM IT MAY CONCERN

On 13 August 1956 I was the Operations Duty Officer at NAS Patuxent River. At approximately 0900 I was standing on the steps at the Operations Building, facing the parking lot, when I observed an A4D with Orange markings descending at approximately a 35 degree angle. I immediately headed for the crash phone to alert the Boat House and other activities involved. While proceeding into the building I saw the aircraft disappear behind the bluff at the approach end of runway 13 and the ensuing splash. I did not note, particularly if the gear was up or down. The attitude of the aircraft until it disappeared from view appeared flat.

(b) (6)

LT

USN

21

Enclosure (7)



STATEMENT OF WITNESS TO CRASH OF A4D-1 ON 13 AUGUST 1956

I was the pilot of an F2H-2 taxiing for take-off at about 1000 on 13 August. The duty runway was 9, and I had been cleared to taxi from the diagonal taxiway down the duty runway to the take-off position. As I started down the duty runway I saw an A4D with tanks on enter the breakup slot for runway 9. The airplane had the landing gear down as it entered the breakup slot, and appeared to be at the normal landing gear down speed. I did not notice if the landing flaps were down. The A4D was cleared to break by the tower. Since I was still taxiing on the duty runway I watched the A4D as it turned downwind. It appeared to be squared away on the downwind leg for runway 9, with at least 1,000 feet of altitude. Shortly thereafter, the A4D began an abrupt descent at an angle estimated at 40° - 45°. There was no apparent change in airplane attitude or course during the descent and the airplane remained in approximately a level attitude. The drop tanks were not jettisoned and no radio transmissions were heard from the A4D. Shortly before the airplane disappeared from sight I advised the tower to check the A4D downwind.

(b) (6)

CDR, USN

22



STATEMENT OF CDR (b) (6) USN

I was at the pistol range, in charge of a firing party, on the morning of the A4D crash. I finally noticed the low and slow flying jet when it was approximately at 300 feet altitude and about at the one o'clock position. It was apparent, immediately, to me that he would never make the field. The plane was in a nose-up attitude, slow (100-110 kts) and descending rapidly at an angle of 40° to 45°. My reference line for the estimate was the top horizon of the pistol butts. I would estimate the aircraft to have been at a distance of 200 yds, and flying perpendicular to the axis of the pistol range.

I exclaimed that he was not going to make it and started running to the left in order to get around the end of the butts. Before reaching the end of the butts, I heard the crash and as the area came into my view, I saw spray, debris, and the rapidly settling tail section of the A4D. Two objects were observed flying forward. One appeared to be the canopy which sank immediately. The other was a small, dark, tank like object, which remained afloat, ahead and to the right of the crash.

While I was running along the outside of the pistol butts, a helicopter passed low overhead and discharged a man into the water. He could be seen examining different pieces of debris. Within a minute, another helicopter (Marine) discharged a man into the same area. A few minutes later a seaplane taxied into the slick and cut its engines. Later the men in the water were observed boarding the plane. After a few more minutes, a small boat from the Flight Test basin entered the area and about ten minutes after the crash, the crash boat came from the Solomon side. (b) (6)

23

Enclosure (9)

GENERAL INSTRUCTIONS

- This report shall be filed in the event of an aircraft accident/incident which involves one or more of the following:  
Death  
Injury  
Bail-out or Ejection (attempted or successful)  
Wherever physiological or psychological factors are involved  
Aircraft Ground Accidents resulting in serious injury
- Completion of the form shall be the responsibility of the flight surgeon
- For type accident and damage code refer to OPNAV INSTRUCTION 3750.6A.
- This form shall be prepared in quadruplicate. One copy shall be turned over to the Aircraft Accident Board (or the Survival and

Intelligence Officer in the case of combat incidents), and the original shall be air mailed (regular mail within 250 miles of Washington, D.C.) direct to Chief of Naval Operations (OP-57) Navy Department, Washington 25, D.C. within 4 working days following the accident. The third copy shall be mailed direct to Safety Equipment Branch, BUAER, Navy Department, Washington 25, D.C. The fourth copy shall be forwarded direct via air mail (regular mail within 250 miles of Norfolk, Va.) to the U.S. Naval Aviation Safety Activity, Naval Air Station, Norfolk 11, Virginia. Where more than one aircraft is involved, separate forms must be completed for each aircraft wherein one or more of the requirements in paragraph 1. above are applicable. (Additional copies may be prepared for use of squadron flight surgeons and other interested individuals)

1. FROM (Only if station address)		2. PERMANENT		3. ACCIDENT OCCURRED (Geographic location)		4. TIME (Local)		5. DATE	
NavAirTestCen, PaxRivMd.		9-56		N.A.S. Patuxent River, Md.		1000		8-13-56	
6. PLANE COVERED BY THIS REPORT		MODEL		NO. OCCUPANTS		UNIT OPERATING AIRCRAFT		TYPE ACCIDENT	
A4D-1		137816		1		Flight Test Division, NATC		B-4	
7. OTHER PLANE (if involved)		MODEL		NO. OCCUPANTS		UNIT OPERATING AIRCRAFT		DAMAGE	
8. NAME OF PILOT IN CONTROL OF AIRCRAFT AT TIME OF ACCIDENT/INCIDENT (Last, first, middle)						UNIT PILOT ATTACHED TO			
LONG, John Oglesby, Jr.						Flight Test Div., NATC			
9. FLIGHT SURGEONS CHECK LIST		<input type="checkbox"/> ALL PARTS OF FORM COMPLETED		<input type="checkbox"/> SURVIVORS NARRATIVES		<input type="checkbox"/> PHOTOS AS NEEDED		<input type="checkbox"/> RECOMMENDATIONS	
								<input type="checkbox"/> COPIES FURNISHED	
10. REPORT FILED BY		SIGNATURE		DATE					
(b) (6) CDR		MC 100N		8-21-56					
C. H. DUEFELDT, RADM		SIGNATURE		AUG 21 1956					
		COMMAN							
12. <input checked="" type="checkbox"/> AIRCRAFT ACCIDENT <input type="checkbox"/> AIRCRAFT INCIDENT <input type="checkbox"/> COMBAT INCIDENT <input type="checkbox"/> GROUND ACCIDENT									

13. ACCIDENT DESCRIPTION

INCLUDE HERE A PARAGRAPH GIVING A BRIEF BUT FACTUAL ACCOUNT DESCRIBING THE ACCIDENT/INCIDENT. INCLUDE SUCH CAUSES AS KNOWN, ESTIMATES OF "G" FORCES, ANGLES OF IMPACT, SPEED ON IMPACT, ATTITUDE ON IMPACT, ETC. ATTACH PHOTOGRAPHS WHEN PERTINENT.

See attached report.

24

14. PILOT FACTORS (Check pertinent pilot factors listed below)

	PILOT	CO-PILOT		PILOT	CO-PILOT
IN CONTROL AT TIME OF ACCIDENT/INCIDENT	X		HYPOXIA SUSPECTED	No	
AMOUNT OF FLIGHT TIME IN LAST 24 HOURS	0		CARBON MONOXIDE POISONING SUSPECTED	No	
NUMBER OF FLIGHTS IN LAST 24 HOURS	0		FAULTY VISION	No	
NUMBER HOURS DUTY IN LAST 24 HOURS	1.5		AEROEMBOLISM	No	
HOURS SINCE LAST FULL MEAL	2.5		BLACKOUT, GREYOUT, REDOUT	No	
TIME AT CONTROLS THIS FLIGHT	30 min		VERTIGO	No	
TOTAL FLIGHT TIME	4592.5		NIGHT BLINDNESS	No	
TOTAL FLIGHT TIME IN MODEL *	21.9		FATIGUE	No	
NUMBER PREVIOUS ACCIDENTS	1		DOMESTIC DIFFICULTIES	No	
DATE OF LAST ACCIDENT	5-11-55		UNFAMILIARITY IN TYPE AIRCRAFT	Yes	
NUMBER DAYS GROUNDED IN LAST MONTH	0		ANXIETY REACTION	No	
DATE LAST LOW PRESSURE INDOCTRINATION	2-4-54		LAST CER (date and score)	11-8-55	+ 12
AMOUNT SLEEP IN LAST 24 HOURS	Approx. 8		OTHER PERTINENT FACTORS IN ACCIDENT (describe below)		

15. COMMENTS ON ITEMS CHECKED UNDER ITEM 14 WHICH ARE PERTINENT TO ACCIDENT/INCIDENT. WHERE APPLICABLE, COMMENT BELOW ON ANY OF THE ABOVE FACTORS AFFECTING CREW MEMBERS OR PASSENGERS

\* Pilot had received a complete cockpit check out in emergency procedures on 10 Aug 1956.



## DIRECTIONS

1. Use separate form for each person.
2. Under Injury Class, use following key:

Class "A" Fatal injury. is considered for reporting procedure as one that results in death prior to submission of the Aircraft Accident Report.  
Class "B" Critical injury is considered for reporting procedure as injury which threatens to result in death either from injuries sustained in the accident or from complications thereof. Critical injuries resulting in death within 30 days shall be reported by letter to the original addressee.  
Class "C" Serious injury is considered for reporting procedure as injury less than critical but definitely requiring five or more days hospitalization involving medical treatment but from which the individual will be expected to recover. Unsuspected critical conditions or complications erroneously

listed in this category which result in death within 30 days shall be reported by letter to the original addressee.  
Class "D" Minor injury is considered for reporting procedure as any injury less than serious.  
Class "E" No injury.  
Class "F" Unknown injury - lost and presumed drowned.  
Class "G" Unknown injury - missing.  
3. Under disposition, use following key:  
"E" - Uninjured  
"G" - grounded  
"R" - treated and returned to duty  
"H" - hospitalized  
"Y" - remains recovered  
"Z" - remains not recovered

1. NAME <b>LONG, John Oglesby, Jr.</b>		2. DUTY ABOARD PLANE, ON DECK/GROUND <b>Pilot</b>		3. RANK/RATE <b>LT</b>		4. AGE <b>34</b>		5. WEIGHT <b>155</b>		6. HEIGHT <b>68"</b>	
7. POSITION OCCUPIED AT TIME OF ACCIDENT <b>Cockpit</b>				8. INJURY CLASS <b>A</b>				9. DISPOSITION <b>Y</b>			
11. SAFETY EQUIPMENT											
SHOULDER HARNESS	MODEL/TYPE <b>A4D-1</b>	AVAILABLE	USED	NOT USED	DAMAGED	LOST	WAS OXYGEN BEING USED AT TIME OF ACCIDENT				
LAP BELT	<b>A4D-1</b>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
INERTIA Integrated torso Harness		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		PREOXYGENATION				
HELMET	<b>APH-5</b>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				
OXYGEN MASK	<b>A-13A</b>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		IF YES, OXYGEN SUPPLY PRESSURE PRIOR TO FLIGHT <b>1800</b> PSI				
GOOGLES							AT TIME OF ACCIDENT				
SHOES (type)	<b>Field</b>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>				WAS OXYGEN EQUIPMENT PRE-FLIGHTED BY PILOT				
FLIGHT SUIT, OTHER THAN "G" (type)	<b>Summer</b>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				
EXPOSURE SUIT (type)	<b>Life Preserver MK1B</b>	<input checked="" type="checkbox"/>					IF SHOULDER LOCKED UNLOCKED TIGHT SLACK				
OTHER (specify)							HARNESS USED <input checked="" type="checkbox"/> LOCKED <input type="checkbox"/> UNLOCKED <input checked="" type="checkbox"/> TIGHT <input type="checkbox"/> SLACK				
12. COMMENT ON EFFECTIVENESS (Entries of "No," "None," "as designed," etc., will not be accepted. If any equipment failed, describe failure and probable cause. Use additional sheet, if necessary.) <b>See attached sheet.</b>							ON IMPACT SAFETY BELT LOCKED TIGHT SLACK				
							<input checked="" type="checkbox"/> LOCKED <input checked="" type="checkbox"/> TIGHT <input type="checkbox"/> SLACK				

IN CASE OF BURNS, FREEZING, OR FROSTBITE, LIST ALL CLOTHING WORN. USE ADDITIONAL SHEET, IF NECESSARY.

13. POST CRASH EXAMINATION	
IF DEAD, LIST PRIMARY CAUSE (multiple extreme, as state) <b>Drowning</b>	INTERNAL INJURIES <b>?</b>
AUTOPSY FINDINGS, IF PERFORMED <b>Supplemental report to follow.</b>	IF HOSPITALIZED, GIVE DIAGNOSIS <b>PLAC</b>
ESTIMATED LENGTH OF HOSPITALIZATION	LIST PRE-EXISTING PHYSICAL DEFECTS PRESENT AT TIME OF POST CRASH EXAMINATION (as condition pre-exists) <b>None known.</b>
CARBON MONOXIDE-NAME COHD TEST-RESULTS <b>Not received this date</b>	
IF GROUNDING, REASON	ESTIMATED LENGTH OF GROUNDING

14. INJURIES												
Chemical	DEGREE	1ST	2ND	3RD	1ST	2ND	3RD	1ST	2ND	3RD	CARBONIZATION ENTIRE BODY	
	AREA	HEAD (ventral)	(dorsal)	TRUNK (ventral)	(dorsal)	EXTREMITIES (upper)	(lower)					
<input type="checkbox"/> FROSTBITE		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
UNCONSCIOUSNESS <input checked="" type="checkbox"/> SHORT DURATION-LITTLE SIGNIFICANCE <input type="checkbox"/> OTHER (time) <b>Unknown, but highly probable.</b>												
HEAD	CEREBRAL CONCUSSION	<input type="checkbox"/> MINOR	<input checked="" type="checkbox"/> SERIOUS	<input type="checkbox"/> CRITICAL	<input type="checkbox"/> FATAL	MINOR FACIAL INJURIES			MAJOR FACIAL INJURIES			
						<b>Contusions and Lacerations</b>						
INJURIES	MINOR EYE INJURIES	<input type="checkbox"/> RIGHT EYE	<input type="checkbox"/> LEFT EYE	MAJOR EYE INJURIES			<input type="checkbox"/> RIGHT EYE	<input type="checkbox"/> LEFT EYE				
TYPE	SKULL	VERTEBRAE (specify no.)				SHOULDER	RIBS	PEL. VIS	UPPER ARM/LOWER ARM	HAND	UPPER LEG/LOWER LEG	FOOT
BONES	CRANIAL FACIAL	CERV.	THOR.	LUMBAR	SACRAL	COCCYX	GIRDLE					
SIMPLE FRACTURE												
COMPOUND FRACTURE												
EXPRESSED FRACTURE												
DISLOC.	JAW								SHOULDER	ELBOW	WRIST	HIP
CAUTION												ANKLE
AMPUTATIONS - STATE PARTS												

AREA OF INVOLVEMENT	LACERATIONS			CONTUSION			ABRASIONS			<input checked="" type="checkbox"/> DROWNED	SHOCK	EXPOSURE
	MILD	MODERATE	SEVERE	MILD	MODERATE	SEVERE	MILD	MODERATE	SEVERE			
HEAD	VENTRAL	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>				<input type="checkbox"/> MILD	<input type="checkbox"/> MILD
NECK	DORSAL										<input type="checkbox"/> MODERATE	<input type="checkbox"/> MODERATE
THORAX	VENTRAL			<input checked="" type="checkbox"/>							<input type="checkbox"/> SEVERE	<input type="checkbox"/> SEVERE
ABDOMEN	DORSAL											
EXTREMITIES (upper)		<input checked="" type="checkbox"/>										
EXTREMITIES (lower)		<input checked="" type="checkbox"/>										

15. CAUSE OF INJURIES (Give opinion as to cause of each injury indicated above. Give specific parts of aircraft involved. Entries of "No," "None," "Sustained on impact," or "Undetermined" with no amplification will not be accepted. Use additional sheet, if necessary.)

See attached sheet.

UNIT **NavAirTestCent**  
 DATE ACCIDENT **8-13-56**  
 MODEL **A4D-1**  
 BU. NO. **137816**

## DITCHING AND WATER CRASH REPORT


<input type="checkbox"/> 1. CONTROLLED DITCHING		<input checked="" type="checkbox"/> 2. WATER CRASH													
3. WEATHER		WIND VELOCITY (Knots) (air temp °F) (water temp °F)													
SEA <input checked="" type="checkbox"/> SLIGHT <input type="checkbox"/> MODERATE <input type="checkbox"/> ROUGH		SE 4 + 80 + 70													
4. PROCEDURES															
CANOPY		DITCHED													
<input type="checkbox"/> JETTISONED		<input type="checkbox"/> ON <input checked="" type="checkbox"/> OFF													
<input type="checkbox"/> OPEN		<input type="checkbox"/> UP <input checked="" type="checkbox"/> DOWN													
<input checked="" type="checkbox"/> CLOSED		<input type="checkbox"/> UP <input type="checkbox"/> PARTIAL <input checked="" type="checkbox"/> FULL													
		<input checked="" type="checkbox"/> CROSS WIND													
5. IMPACT (Estimated)															
ATTITUDE	ANGLE	SPEED (Knots indicated)	STOPPING DISTANCE (ft.)												
Nose Up	Approx. 45°	?	?												
		NO. OF IMPACTS	TIME A/C FLOATED (Sec)												
		Two	Sank immed.												
6. EXIT															
NAME		BILLET	UNDERWATER												
A. LONG, John Oglesby, Jr.		PILOT	No												
B.			None												
C.															
D.															
Difficulties Denote below under A, B, C, and D															
Pilot was still in cockpit with Lap Belt and Shoulder Harness partially detached. Right foot moderately entangled in wreckage. Death due to drowning.															
26															
7. SURVIVAL EQUIPMENT															
SHOES		GLOVES		LIFE VEST		EXPOSURE SUIT		RAFT		USED TO ATTRACT ATTENTION					
TYPE	DAMAGED	TYPE	DAMAGED	TYPE	DAMAGED	TYPE	DAMAGED	TYPE	DAMAGED	DYE	FLARES	FLASHLIGHT	MIRROR	GUN	RADIO
A. Field	No			MK 3B	No			Not Used	No	No	No	No	No	No	No
B.															
C.															
D.															
8. LIST CAUSE OF DAMAGE, IF ANY, TO SURVIVAL EQUIPMENT (include photo of damage) (use additional sheet, if necessary)															
No damage to survival equipment - None used															
9. LIST ANY DIFFICULTIES OR FAILURES IN USE OF SURVIVAL GEAR (use additional sheet, if necessary)															
Failure to use probably due to unconsciousness and drowning.															
10. TIME IN RAFT				TIME IN WATER				METHOD OF RESCUE							
Not used				1 1/2 hours				Rescue removed by divers.							
11. LIST EQUIPMENT DROPPED TO SURVIVORS; STATE IF USED EFFECTIVELY (use additional sheet, if necessary)															
None															
12. LIST ALL ITEMS IN SURVIVAL KIT WHICH WERE USED - EFFECTIVENESS (List those needed items which failed or were lost - Recommendations) (Use additional sheet, if necessary)															
None used															
13. INCLUDE SURVIVORS NARRATIVES															
None															



LT John O. LONG, Jr., (b) (6) U. S. Navy, left the flight line at 0930 and was airborne at approximately at 0935. Take-off was normal and no radio transmissions were received prior to his call for a break over duty runway at about 0955. His call for the break was routine and no mention of emergencies or malfunctions was made. The break was observed to be normal and wheels and flaps were extended preparatory to landing on runway 9. During the down-wind leg, he was observed to develop a high rate of sink with the aircraft in a level attitude. On turning base the rate of sink continued and was estimated to be about 40° to 45°. The aircraft was observed to strike the water in a nose high attitude, nose over, and break up on impact. The wreckage sank immediately. One helicopter pilot nearby proceeded immediately to the site of the crash and observed a helmet and what appeared to be a parachute come to the surface almost at once, however, the pilot failed to appear.

Divers located the wreckage about one hour later and the pilot was found in the cockpit area still attached to the seat by shoulder strap and lap belt attachment. The pilot's right foot and leg were entangled in the wreckage, but were easily freed by the diver, the left lap belt attachment was open. Post mortem examination revealed death to be due to drowning.

Examination of the wreckage revealed the following:

- a. Failure of left shoulder harness attachment. Linkage had pulled free from the attachment to the inertia reel cable.
  - b. Failure of entire bottom of seat.
  - c. Possible failure of left-belt rocket fitting. This fitting was found by divers to be in the open position. It might have occurred during crash or have been opened by the pilot. The latter is extremely doubtful.
  - d. The visor and visor shell of the APH-5 helmet had been wiped off on impact. The chin strap had failed at the left attachment; otherwise, the helmet was intact.
  - e. Though the oxygen mask yoke suspension remained attached to the helmet, the Al3-A oxygen mask was missing.
  - f. Oxygen mask and hose were separated.
- (b) (5)
- 

(b) (5)



Supplemental reports will be submitted.

(b) (6)



CONFIDENTIAL

28

PAGE 2 OF 2

Enclosure (10)



STATEMENT OF MAJ (b)(6) PERTAINING TO CRASH OF  
A4D-1, BUNO 137816  
on 13 AUG 1956

1. At 1600 on 13 Aug 1956 I examined the left and right cockpit consoles of A4D-1, BuNo 137816. The following was noted:

- a. The throttle was in the cutoff position.
- b. Wing fuel pump transfer switch was off.
- c. External fuel tank pressurization was on.

2. The throttle friction wheel in 816 provided no friction when the wheel was rotated aft. A peculiarity of this throttle quadrant was a tendency toward throttle stickiness when the friction wheel was set for about average throttle friction. As a result I flew this airplane with somewhat less throttle friction set than I did on other airplanes. Also, there was no lip on the idle stop which made it quite possible for the throttle to slip off the idle stop and on around to the cut-off position if throttle aft motion was fast and positive. While this never happened to me, I have been able to simulate it in another A4D-1 with average throttle friction cranked in.

3. In 816 there is a red cover-guarded wing fuel pump on-off switch installed to permit attaining an artificial or emergency c.g. condition for test purposes. It is necessary to lift the cover guard and throw the toggle switch forward to shut off wing fuel transfer. This switch is located on the starboard console at the extreme aft end--well out of a pilot's normal field of vision. The pilot is reminded by two separate sources when the pumps have failed or the switch is off. They are:

- a. The marker beacon red light is also wired to the pump and would burn steadily.

- b. The fuel quantity gauge would read fuselage fuel only when fuselage fuel was down to 1100 lb.

In the event of failure of the wing fuel transfer pump in an A4D-1 airplane the only usable fuel is the approximately 1700 lb of fuselage tank fuel. If the marker beacon light has burned out, the pilot is unaware of the failure until the fuel gauge unwinds to 1100 lb.



4. External tank fuel transfer is effected by flipping the fuel tank pressurization switch to on. The external tanks are then pressurized by engine bleed air and the fuel transfers to the wing tank. If the wing transfer pump is off or has failed, external tank fuel will continue to transfer to the wing until the wing is full at which time engine air is then vented overboard. Leaving the pressurization switch on when the wing fuel transfer pump has failed or when all external fuel has been transferred results simply in wasting engine power.

5. LT Long received two cockpit checkouts from me. The first was last winter and the second was Monday, 6 August 1956.

(b) (6)

V MAJ, USMC

30



TO WHOM IT MAY CONCERN:

At approximately 0900 EST 13 August 1956 while standing on the steps (adjacent to the parking area) of the MAS Operations building I saw a jet aircraft in a descent just prior to crashing in the water offshore from the approach end of runway 13. When I first observed this aircraft I would estimate its altitude to be approximately 100 feet. The aircraft was in a flat to slightly nose down (mushing) attitude with the gear extended. It was heading in a southwesterly to westerly direction. I did not see the aircraft when it made contact with the water as it disappeared behind the bluff to the approach end of runway 13.

(b) (6)

LCDR

USN

31

Enclosure (12)

STATEMENT OF (b) (6) AN, USN

At 0925, LT Long came out to the plane, A4D BuNo 137816. He walked around it once then got in the cockpit. I helped strap him in and handed him his pilots handbook and oxygen mask which he set on the right console. We gave him a normal start and directed him out to the taxi-way. During taxi-out, I stopped LT Long because out fuel dripping. (b) (6) and a Douglas mechanic checked it and it was only coming out of the fuel vent.

(b) (5)

Usually, he asked either myself or one of the Douglas mechanics how the plane was. That morning he did not. When LT Long walked around the plane, he didn't check his slats, flaps, etc., like he usually did. During turnup, LT Long always checked his dive brakes, elevators, etc. That morning he did not check anything. LT Long always came out fast when I taxied him out. That morning he crept out. Always before when I got LT Long on the taxi-way and gave him the thumbs up, he always returned it, that morning he only nodded,

(b) (6)

32

Enclosure (13)



STATEMENT OF (b) (6)

DOUGLAS MECHANIC

On August 13 at approximately 1000 I was walking in an easterly direction just opposite the Structure Shop at Flight Test when I happened to look toward the river and saw the A4D, which subsequently proved to be BuNo 137816, crash. My first impression was that the airplane was making a low altitude speed run because, when I first saw it, it was at an altitude of no more than 150-200 feet. The ship was descending at a very high rate and at an angle that I would say was between 30° and 45°. It was heading very close to due west. I think that the gear was up, but am not positive. I am almost certain that the airplane was under control in the two or three seconds that I saw it before it ditched. I could see the blue drop tanks fairly clearly so I am sure the wings were very close to level. The nose was in a slightly high attitude. There was considerable noise from the shops in my vicinity but I do not think the engine was running. I did not hear it. The ship disappeared behind some barges when about 15 feet off the water so I only saw the spray from its actual contact.

(b) (5)

(b) (6)

33

Enclosure (14)

21 August 1956

From: (b) (6) AO-1, IRB, Service Test  
To: CDR (b) (6) Flight Test

Subj: A4D Crash, Observation of

1. While walking between hangars 110 and 111 I observed an aircraft disappear behind the barge toward the water and saw a splash approximately twenty feet above the barge in a northwest direction.

2. The moment of observation was so brief that I was unable to determine the type or attitude of the plane at the time of contact with the water. Jet aircraft were turning up in Flight Test parking area so I was unable to determine whether the engine was running or not at the time of the crash.

(b) (6)

34

Enclosure (15)



STATEMENT OF (b) (6) AD3, USN

On the morning of 13 August 1956, I made a scheduled run to the small arms firing range. I parked the van in the parking area directly across the road from the firing range to wait for the men returning to hangar 305. At approximately 1005, while seated in the tractor, I observed an airplane approaching from about one o'clock. I can give no estimate of its altitude at that time. He appeared to be fish tailing badly and losing altitude rapidly. He seemed to have had power failure as his engine sounded as though it was turning over very slowly. It looked to me like he was heading in the general direction of my van. Since I preferred to be out of the way when the aircraft hit, I got out of the van and ran toward the water. The next time I looked up, the aircraft was over the water and falling nearly straight down. When it hit the water, it was in an extremely nose high attitude. Upon contact with the water, the aircraft flattened out on its underside and the nose plunged under. In about three seconds, the entire aircraft was submerged. Within twenty or thirty seconds, the rescue helicopter was at the scene.

(b) (6)

AD3, USN

(b) (6)

AD3

35

Enclosure (16)

16 August 1956

TO WHOM IT MAY CONCERN:

After checking runway lights, I was driving on the road near Langenfelder's pump house where barges are being unloaded, when I noticed a plane coming in flying low at approximately a 30 degree angle. The time was approximately 1000. I watched the plane because it was flying unusually low. To my knowledge, the plane's motor was not running. This occurred on Monday 13 August 1956.

The plane went into the water approximately 500 feet off of the pistol range. After hitting the water, the plane disappeared within one half a minute. The next thing I saw was what appeared to be a large spray of steam.

Mr. (b) (6) states the wheels were down.

(b) (6)


(b) (6)

ingman Cable splicer

36


enclosure (17)





Enclosure (19)

# PLATE 20




Enclon 10-1-71





Enclosure (15).




enclosure (1),






Enclosure (18). (17.1)




Enclosure (18).<sup>6</sup> Fig. 5







enclosure (10), fig. 5

Enclosure 10/1/12















Enclosure (18). 18.





enclosure 101, 102, 103




Enclosure (18), 11.












FRONT MAIN  
BEARING

25





CHARTER MOUNT  
BEARING




52





CENTER MAIN  
BEARING  
~~BEARING~~ DISSEMPLED




54

OIL SEAV PUMP SCREEN



A4D-1 BONO 137816

DAX






ENGINE DRIVEN FOEC




56






40503



Asst. Dir. Gen. Inv.  
Adm. Serv. Div.  
Bldg. 131216

58














61



enclosure (18). 118. 33









reloans (18) 1971

Handwritten notes on a piece of paper, possibly a receipt or inventory list, with some illegible text and a date that appears to be 10/10/71.



68